TIB's

✦TECHNOPEDIA✦

Doc. #	Description
20441	Air Compressor Compatability
20433	PS8050 220vac Jumper Installation
20367	GR2700 Trail Edge Shadow
20278	RG/RC Parts Availability
20275	RG/RC Support Discontinuation
20270	GR3770 Technical Manual Update
20269	GR3770 Ink Overflow
20268	Damage to Solenoids in Test Mode
20088	GR Separation Air Hose
20087	Preventative Maintenance Schedules
20030	TM5000 ROMs
20029	GR Pickup Pad U; ADF
20028	GR Sheet; Guide Plate
20025	GR Bracket K / Magnet Catch
20024	PROM Reburn Program
20008	New TR ROM's / Master Cut Length
20007	NC Guide Rule Decal on Holder Ring
20006	Important ROM Compatibility Issues - GR/TM5000
20002	TR Mylar Sheet; Write Roller
20001	Modification Procedures GR3770 Black Drum
19511	TechFlash
19504	ROM Compatibility List
19503	Modification of Link Plate; ADF
19502	TR1510 Modification of Master Clamp Plate
19443	GR3770 Clamp Plate Base Asssembly
19442	GR3770 Set-Up Procedures
19441	Mylar Sheet; Load Roller; Installation to a TR1510
19440	Digitizer III Installation to a GR3770
19437	GR3770 Clamp Plate Base Assembly
19434	Change of Zoom Function
19272	Master Loading Modification
19271	AR8000 Mounting Bracket Adjustment Procedure
19240	GR Receiving Area Change (old TIB-146)
12145	TR1510 Ink Control Errors (old TIB-145)
12144	SF Return Motor Ass'y Modification (old TIB-144)
12143	Improve Master Removal (old TIB-143)
12142	Feed Clutch (old TIB-142)
12141	New Type Stripper Unit GR (old TIB-141)
12140	Copy Quality (old TIB-140)
12139	Paper Feed Errors (old TIB-139)
12138	Screen Hanger (Lower) (old TIB-138)
12137	Feed Tray/Side To Side Registration (old TIB-137)
12134	Ink Migration (old TIB-134a)
12136	Duo Processing Mode (old TIB-136)
12135	Upper Limit Sensor (old TIB-135)
12133	Ink Migration (old TIB-133)
12132	GR Series First Paper Feed Adj. (old TIB-132)
12130	GR Ser. Flatbed Unit - CE Reg. (old TIB-130)

RISO RISO RISO RISO RISO RISO RISO RISO RISO RISO RISO RISO RISO RISO

TIB's

✦TECHNOPEDIA✦

Doc. #	Description
12129	Electromagnetic Influence - CE (old TIB-129)
12128	GR-17mm Voids on Sides of Copy (old TIB-128)
12127	GR Print Magnification (old TIB-127)
12126	GR Print Cylinder Set-Up (old TIB-126)
12124	Machine Stops In Cycle / ADF Orig. Jams
12123	Vacuum Conveyor Belt Stretch (old TIB-123)
12083	Rom Reburn Program (old TIB-83)
12073	Feeding Problems Due To Odd Paper (old TIB-73)
12122	P-Disc Start Time (old TIB-122)
12121	Black Bands (old TIB-121)
12117	Two Up Feature (old TIB-117)
12116	Improved Master Loading (old TIB-116)
12100	Pressure Detection Potentiometer (old TIB-100)
12094	ROM Issues (old TIB-94)
12114	Paper Det. Sensor Cover (old TIB-114)
12120	Paper Feed Tray Support Plates (old TIB-120)
12119	Digitizer Pen Holder (old TIB-119)
12118	RC 6300 Ink Pump Assy; A3 (old TIB-118)
12115	Paper Ejection Improvements (old TIB-115)
12113	Precaution: C-1 Plate (old TIB-113)
12111	Imaging - Loose Connections (old TIB-111)
12110	Drum Locking - Wrong Screws (old TIB-110)
12109	Digitizer III - Technical Notes (old TIB-109)
12108	Insertion Mechanism Indexing (old TIB-108)
12107	Keycard Trouble Shooting (old TIB-107)
12106	Preventative Maint. (old TIB-106)
12104	Insertion Mech. Maint. (old TIB-104)
12103	M60/S60 Application Tips (old TIB-103)
12102	Shipping Protection Tape (old TIB-102)
12101	Disposal System Changes (old TIB-101)
12099	Insufficient Paper Transfer (old TIB-99)
12098	T3 / E03 Errors (old TIB-98)
12097	Drum Lock Will Not Release (old TIB-97)
12096	RA Out Of Box Quality Checks (old TIB-96)
12095	RC Master Disposal Checklist (old TIB-95)
12093	Enhanced Copy Quality Adjs. (old TIB-93)
12092	RC Series Clamp Lubrication (old TIB-92)
12091	RC Series Master Sensor (old TIB-91)
12090	New Thermal Chart (old TIB-90)
12089	Quality Control Unpacking (old TIB-89)
12088	RC Sorter / RC Machine Operation (old TIB-88)
12087	Reinforcing Plate;Drum Holder (old TIB-87)
12086	Clamp Plate Assembly (old TIB-86)
12085	RC Series Wire Harness (old TIB-85)
12084	RG/RC Wire Harness Maps (old TIB-84)
12082	Master Removal Sensor (old TIB-82)
12081	Angular Magnet Plate (old TIB-81)
12080	Master Removal Hook (old TIB-80)

RISO RISO RISO RISO RISO RISO RISO RISO RISO RISO RISO RISO RISO RISO

✦TECHNOPEDIA HOME✦

RISO RISO RISO RISO RISO RISO RISO RISO RISO RISO RISO RISO RISO RISO

TIB's

✦TECHNOPEDIA✦

Doc. #	Description
12079	Pressure Solenoid (old TIB-79)
12078	Sensor Dust Cover (old TIB-78)
12077	Current ETR Issues (old TIB-77)
12076	Drum Related Problems (old TIB-76)
12075	Machine Stops In Cycle (old TIB-75)
12074	Connector Clips (old TIB-74)
12072	Master Wrinkle (old TIB-72)
12071	Copy Quality (old TIB-71)
12070	Paper Detection Sensor Receive (old TIB-70)
12069	Roll Pin Replacement (old TIB-69)
12068	Technical Tips (old TIB-68)
12067	RC Power Supply Units (old TIB-67)
12066	RC Circuit Boards (old TIB-66)
12065	RG Operation Panels (old TIB-65)
12062	Board Compat./Part # Changes (old TIB-62)
12064	RC Cutter Motor Rotates (old TIB-64)
12063	Disposal Spec./Recommendations (old TIB-63)
12061	System Rom Version (old TIB-61)
12060	Master Disposal Jams (old TIB-60)
12059	Wrinkled Masters (old TIB-59)
12058	Spacer Cushion / "O" Ring (old TIB-58)
12057	Tape Sorter Conversion A4/B4 (old TIB-57)
12056	Drum Body Cracking (old TIB-56)
12055	Drum Specifications/Adjustments (old TIB-55)
12054	Post Card/Envelope Attachment (old TIB-54)
12053	T3/Master Cut Malfunction (old TIB-53)
12052	Cutter Assembly (old TIB-52)
12051	IT I/O PCB Modification (old TIB-51)
12050	Drum PCB Cover (old TIB-50)
12049	Modification Of Drum PCB (old TIB-49)
12048	Write Roller (old TIB-48)
12047	A4/B4 Machines (old TIB-47)
12046	Fuse Panel (old TIB-46)
12037	Separator Spring; Rel Lever (old TIB-37)
12045	IT I/O PCB (old TIB-45)
12044	Vertical Black Dotted Lines (old TIB-44)
12043	Paper Sensors (old TIB-43)
12042	Separator ; Design Change (old TIB-42)
12041	Troubleshooting Ink System (old TIB-41)
12040	Starter Roller; Clamp Plate Base (old TIB-40)
12039	Pickup Roller Assembly (old TIB-39) 27K 04/18/89
12038	Troubleshooting New Style Drum PCB (old TIB-38)
12033	2500 Master Roll Brake Ass'y (old TIB-33)
12036	New Style Write Roller (old TIB-36)
12035	Master Holder (old TIB-35)
12034	Feed Roller; Stopper Cap (old TIB-34)
12032	2500 Upper Discharge Roller (old TIB-32)
12031	Sticker Sheet/Upper Discharge Roller (old TIB-31)

✦TECHNOPEDIA HOME✦

TIB's

✦TECHNOPEDIA✦

Doc. #	Description
12030	Troubleshooting Guide II (old TIB-30)
12029	Separator Return Spring; PJR (old TIB-29)
12028	Disposal Roller; Modification (old TIB-28)
12027	2700 ADF; Modification (old TIB-27)
12026	Drum PCB; Design Change (old TIB-26)
12025	Clamp Guide; Design Change (old TIB-25)
12017	Pickup Rollers; Design Change (old TIB-17)
12023	Image Scanner Reduction (old TIB-23)
12024	Drum - P Master; Modification (old TIB-24)
12019	Reference Chart For TPH Setting With H Master
12021	Resetting Micro Processor Memory (old TIB-21)
12020	3500 Manual Adjustments; Temporary (old TIB-20)
12016	Troubleshooting Aid For Original Jam (old TIB-16)
12018	257 Image Scanner; Adjustments (old TIB-18)
12014	Pressure Hook And Lever;Design Change
12013	Upper Cutter; Modification (old TIB-13)
12015	Suction Unit; Design Change (old TIB-15)
12012	Troubleshooting Aid For Cutter Assembly
12011	Write Roller; Design Change (old TIB-11)
12010	Troubleshooting Aid For T-3 (old TIB-10)
12005	Disposal Unit; Mod Kit 1&2 (old TIB-5)
12008	Pulse Motor Cement Resistor New Type
12004	Troubleshooting Guide (old TIB-4)
12007	Jump Wire Guide (old TIB-7)
12002	Bracket; Clamp Motor (old TIB-2)
12006	WP Disc Modification (old TIB-6)
12003	IT I/O PCB (old TIB-3)